CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD - SAN DIEGO REGION

FACILITY INSPECTION DATA ENTRY FORM

INSPECTION DATE: $\frac{12/22/08}{100000}$ TIME: $\frac{9:30am}{100000}$ WDID: $\frac{900000}{100000}$	1871 ORDER NO. 61-3 FILE NO. 731059	
FACILITY REPRESENTATIVE(S) PRESENT DURING INSPECTION:	Ryan Armstrong	
NAME OF OWNER, AGENCY OR PARTY RESPONSIBLE FOR DISCHARGE Armstrong Farms Ex. 6 Personal Privacy (PP)	Ex. 6 Personal Privacy (PP) OWNER CONTACT NAME AND PHONE # Sawle FACILITY OR DEVELOPER CONTACT NAME AND PHONE # Value Contact CA FACILITY CITY AND STATE	
APPLICABLE WATER QUALITY LICENSING REQUIREMENTS (CHECK ALL THAT APPLY) MS4 URBAN RUNOFF REQUIREMENTS NPDES NOS. CAS0108758, CAS0108740 or CAS0108766 CONSTRUCTION GENERAL PERMIT ORDER NO. 99-08-DWQ, NPDES NO. CAS000002 CALTRANS GENERAL PERMIT ORDER NO. 99-06-DWQ, NPDES NO. CAS000003 INDUSTRIAL GENERAL PERMIT ORDER NO. 97-03-DWQ, NPDES NO. CAS000001 GENERAL OR INDIVIDUAL WASTE DISCHARGE REQUIREMENTS OR NPDES GENERAL OR INDIVIDUAL WAIVER OF WASTE DISCHARGE REQUIREMENTS SECTION 401 WATER QUALITY CERTIFICATION CWC SECTION 13264		
"A" type compliance—Comprehensive inspection in which samples are taken. (EPA Type S) "B" type compliance—A routine nonsampling inspection. (EPA Type C) Noncompliance follow-up—Inspection made to verify correction of a previously identified violation. Enforcement follow-up—Inspection made to verify that conditions of an enforcement action are being met. Complaint—Inspection made in response to a complaint. Pre-requirement—Inspection made to gather info. relative to preparing, modifying, or rescinding requirements. Miscellaneous—inspection type is not included on this list, may include NOT, NEC, NONA or other types Pretreatment Audit (every five years) Pretreatment Compliance (yearly except audit year)		
INSPECTION FINDINGS		
Were violations noted during this inspection? (Yes/No/Review Sample	e Results)	
Were samples taken? (N=no) If YES then, G= grab or C= Composite and attach a copy of the sample results/chain of custody form		
I. COMPLIANCE HISTORY:		
Nov. R9-2008-0149 issued 11/21/08 for V No. 3, Resolution No. R9-2007-0104	iclations of Conditional Waiver	
II. FINDINGS Staff did not observe Stormwater of the 10 mouveryment measures are in place to water back onto the site, and prop	divert Stormwater & organs	

FACILITY: Amustrong Farms (WDID)		
\cup		
the site. The owners have consulta	A /1	
regarding the design of permanent poras to collect Stermwater + proces		
permanent management measures is	for composting areas.	
Or Co. C. A. I.		
Staff informed the owners of its in	ant to issue sitz-speafic	
waste discoverge requirements, as	compositing is no longer courred	
0		
III DECOMMENDATIONS AND ADDITIONAL ITEMS FOR I	FOLL OWALD	
III. RECOMMENDATIONS AND ADDITIONAL ITEMS FOR FOLLOWUP		
Temporary BMPs Should be updated to more permanent BMPs.		
Regional Board Staff will meet with	. (1	
discuss plans for permanent BMP	s and water detention pands.	
SWPPP Reviewed: YES NO		
COPY PROVIDED TO OPERATOR? YES NO COPY TO BE MAILED? YES NO		
COMMENTS REGARDING INSPECTION (FOR ENTRY INTO SWIM, such as notes on photos, file locations and/or samples):		
Comments of the comments of the complete of the complete of the comments of the complete of th		
RESPONSIBLE PARTY SIGNATURE	INSPECTION DATE	
t) Sha	Dic. 22, 2008	
STAFFINGPECTOR SIGNATURE	INSPECTION DATE	
IV. (For internal use only)		
Reviewed by Supervisor:	Date	
cc: City Con	itact	
Program: NPDES STORM NON15-WDR 401 NPS TITLE 27 AGT DoD LNDISP PTPRG RCRA SLIC REC		
Inter-office Referral: 1) 2) 3)5)	

S:\Industrial Compliance\Stormwater\inspection Report Form 11-20-02.doc S:\Forms & Templates\Inspection Report Form.doc


Inspection Date: December 22, 2008

Photo shows some of the temporary best management practices installed by the owners to prevent the discharge of waste water from the site. This inspection occurred on a rainy day, and staff did not observe any runoff or discharges of waste water from the site.




Inspection Date: December 22, 2008

This is the same photo shown above at a closer range. The owners installed sand bags as temporary controls for runoff. According to the owners, these temporary measures will remain in place until the permanent best management practices or management measures can be installed.



Inspection Date: December 22, 2008

This photos depicts as earthen trench constructed by the owners to divert storm water and/or waste water back onto the site, and to prevent the illicit discharge of these waters from the site. Staff recommended the owners line the trench to help prevent sediment build-up, and to make this a more permanent management measure.



Inspection Date: December 22, 2008

This photo depicts one of the composting areas. The photo shows that the area is lined with asphalt, preventing infiltration of nutrients into groundwater in this area. Permanent best management practices have not yet been installed in this area due to issues with the machinery used in composting. More permanent measures will be installed once a decision is made regarding the number of detention ponds appropriate for this site.

